


OIL VISCOSITY CHART

Viscosity is the measure of a material's resistance to flow. Viscosity is a result of the internal friction of the material's molecules. Materials with a high viscosity do not flow readily; materials with a low viscosity are more fluid. It is also a measure of the ease with which a liquid can be poured or stirred. The higher the viscosity, the less easily a liquid pours.



G. P. Reeves Inc. 12764 Greenly Street Holland, MI 49424

Phone: 888.399.8893

Fax: 616.399.8867

Web Site: <http://gpreeves.com>